

Newmarket/Hobson Bay wet weather sampling progress August 2020

This map represents data collected during 2019 and 2020. It represents the likely public health risk, with respect to NZ contact recreation guidelines, across Hobson Bay/Waitaramoa as at 19 August 2020 and is subject to change as investigations and corrective actions progress. This map has been prepared by Auckland Council Healthy Waters for the purpose of community engagement addressing this current public health risk. For further up to date information about where to swim, check <u>safeswim.org.nz</u>.

