

Photo Hapua Thrive






Healthy Connections helps

- join the dots
- keep poo in pipes
- keep us safe





Community concerns "STINK" Water Quality www.hapuathrive.nz^{Reserve}

Newmarket

- unpleasant smells and dead eels in the waterways
- Dirty looking water
- Questions whether it was safe to have contact with the water particularly on paddle craft and to eat flounder and other kaimoana
- Questions about children playing in streams, safety of walking school bus and school activities

Hapua Reserve





Newmarket/Hobson Bay wet weather sampling progress August 2020

This map represents data collected during 2019 and 2020. It represents the likely public health risk, with respect to NZ contact recreation guidelines, across Hobson Bay/Waitaramoa as at 19 August 2020 and is subject to change as investigations and corrective actions progress. This map has been prepared by Auckland Council Healthy Waters for the purpose of community engagement addressing this current public health risk. For further up to date information about where to swim, check <u>safeswim.orq.nz</u>.






Newmarket/Hobson Bay dry weather* sampling progress August 2020


This map represents data collected during 2019 and 2020. It represents the likely public health risk, with respect to NZ contact recreation guidelines, across Hobson Bay/Waitaramoa as at 19 August 2020 and is subject to change as investigations and corrective actions progress. This map has been prepared by Auckland Council Healthy Waters for the purpose of community engagement addressing this current public health risk. For further up to date information about where to swim, check safeswim.org.nz.




Water Quality at Kayak steps – dry weather



Dry weather water quality at Hapua Stream



Dry weather water quality at Portland Stream




Safe Networks Sampling & contamination tracking. Progress to March 2023.

Stormwater lines

- - Clean
- Contaminated
- Testing Required
- Other

Stormwater network catchments

- Clean
- Contaminated
- Testing Required
- Other *




Faults Found: 2020 to March 2023

Sub- catchment	Private issues	Private issues resolved	Public issues	Public issues resolved	
Parnell	3	1	9	9	
Нариа	19	17	22	14	
Portland	6	2	9	7	
Newmarket	10	7	21	12	
Waiata	1	1	5	5	
Total	Total 39		66	47	



Modelling Wet Weather Performance 2023




Legend

☐ Each square is the site of an Engineered Over Flow where sewage flows to streams




Modelling Wet Weather Performance 2023 Zoom to Hobson Bay



Legend

☐ Each square is the site of an Engineered Over Flow where sewage flows to streams






Healthy Connections






Stream	Sampling Location	Weather	Number of	E. Coli MPN/100 ml) of Contact recreation trigger (550 MPN/100ml)			Enterococci (MPN/100ml) Contact recreation trigger (280 MPN/100ml)		
Catchment		Conditions*	Samples	Minimum	Maximum	Median	Minimum	Maximum	Median
New Market and Hapua Streams	WIL201 (Kayak Steps)	Dry	30	<100	92,000	630	10	19,000	310
		Wet	49	<100	220,000	7,600	<100	87,000	750
		Neither	16	200	69,000	685	10	13,000	100
Hapua Stream	WIL205 (Bloodworth Park)	Dry	29	100	200,000	20,000	96	15,000	2,000
		Wet	51	1,000	1,100,000	44,000	<100	92,000	3,000
		Neither	14	8,600	200,000	50,500	310	15,000	4,200

Data supplied by Auckland Council 19 August 2020





Completed improvement works: 1. Okahu Separation 2. Glen Innes PSUpgrade

The areas in green have been updated with a detailed model e.g survey information, connections, local networks etc.

EOP's: Newly identified and confirmed decommissioned EOP's

Minor differences: e.g. updated growth projections.

Photo Hapua Thrive





What we want in the short term

Dry weather faults fixed
Routine testing of water
Newmarket Gully
locked in
Increased
understanding of Bay
Further development of
EIWQIP
More information
www.hapuathrive.nz




Photo Hapua Thrive

